

### Request for Delisting Gem Lake from the Minnesota Pollution Control Agency's 303D Impaired Waters List



Pictured – Brian Corcoran, Water Resource Manager, VLAWMO, paddling Gem Lake

Prepared by Tyler Thompson, GIS Watershed Technician, VLAWMO

August, 2017

**Special thanks to:** Kathleen Robins for allowing VLAWMO staff access to her property for sampling, as well as to the Swomley family to allow access to their property for installing Gem's staff gauge

Gem Lake, located in Gem Lake, MN, was assessed in 2009 as not meeting the standards for nutrients pollutants affecting aquatic recreation use and was placed on the MPCA's Impaired Waters List in 2010. Gem had its highest annual average for nutrients in 2009, and, since then, TP levels have significantly decreased to nearly half the MPCA's standard of 60  $\mu$ g/L for shallow lakes consistently for the last 5 monitoring seasons. Chl-a levels have gone above MPCA's standard of 20  $\mu$ g/L for shallow lakes twice since 2009: 24  $\mu$ g/L in 2010 and 23  $\mu$ g/L in 2015. The average level of Chl-a from May, 2010 to August, 2017 has been 15  $\mu$ g/L.

Gem Lake's watershed and catchment area is about 328 acres, and of this, 52.6 acres or 16% of the subwatershed is impervious surface, and just a fraction of that makes its way directly into the lake's basin. Within the Lake's subwatershed, 3.69 acres of U.S. Route 61 drains towards Gem Lake. Since reconstruction of this section of the Highway in 2011, nutrient levels in Gem Lake have dramatically decreased. Reconstruction in this section of the Highway that drains towards Gem Lake, ditches were regraded, erosion issues were mitigated, ditch blocks were installed, and vegetation was established where mowed turf previously existed.

Just to the east of Gem Lake, the sanitary sewer under Scheuneman Road was lined in 2010, which had the potential for impacting nutrient levels in the Lake by mode of shallow ground water transfer before the sanitary sewer was lined. Also in the year 2010, Scheuneman Road south and east of highway 61 was reconstructed, ditches regraded and vegetation established, greatly improving stormwater conditions before discharging by pipe underground to the NB Highway 61 ditch and eventually into Gem Lake. Years after reconstruction, site conditions are much better than before reconstruction.

### By the numbers:

- Gem Lake subwatershed: 328 acres
- Gem Lake basin: 27 acres total, 21 acres open water
- 16% of the land surface in the Gem Lake subwatershed is impervious
- 89 μg/L: the average of TP samples during the 2009 sampling season
- 36 μg/L: the average of ALL TP samples from Gem Lake for the last 8 monitoring seasons, May, 2010 – August, 2017

### Highway 61, MNDOT Project 6222-161, 2011

- Improved grading and removed sediment
- Replaced and improved storm sewer infrastructure
- Ditch block installed in ditches to slow stormwater and increase infiltration before reaching Gem Lake

• Established vegetation (MNDoT seed mix 250) where erosion was once and issue, slowing discharge rates and increasing infiltration in the NB ditches and swales before they flow west to the SB ditch wetland and then into Gem Lake

### Scheuneman Road (north and west of Hwy 61) sanitary sewer lining, 2010

• Lined sanitary sewer lines, potentially ceasing shallow groundwater nutrient loading from leaking lines into Gem Lake


### Scheuneman Road (south and east of Hwy 61) reconstruction, 2010

- Re-grading of the west ditch, including re-seeding and the addition of rip-rap at the end of the ditch. Years later, post-construction, the vegetation is much healthier than before reconstruction
- Storm water from this ditch routes underground and over to the east ditch of the NB lane of Highway 61

Sample Year	TP avg µg/L	% below standard	Sample Year	Chl-a avg µg/L	% below standard
2007	48	2.0%	2007	33	65% above
2008	64	6.7% above	2008	17	15.0%
2009	89	48% above	2009	28	40% above
2010	53	11.6%	2010	24	20% above
2011	32	46.7%	2011	6.4	68.0%
2012	41	31.7%	2012	11	45.0%
2013	35	41.7%	2013	17	15.0%
2014	31	48.3%	2014	8	60.0%
2015	38	36.7%	2015	23	15% above
2016	30	50.0%	2016	18	1.0%
2017 (Aug)	29	51.7%	2017 (Aug)	12	40.0%

**Tables 1 & 2:** Illustrating total phosphorus and chlorophyll-a levels in Gem Lake the last 11 monitoringseasons.

Based on data from the last 8 monitoring seasons, or 76 samples taken per VLAWMO's regularlyscheduled monitoring program, total phosphorus levels in Gem have been reasonably below shallow lake state standard since 2010. Chlorophyll-a levels have been shown to be close to state standard, as well as above standard in 2015 and 2010 since 2009. With the two parameters combined and looking at the trend in water quality data on Gem Lake since monitoring began in 1997 (see appendix A, page 33), the Watershed is asking that Gem Lake be reviewed for removal from the MPCA's 303D Impaired Waters List.



**Figure 1:** Map illustrating Gem Lake's location and subwatershed, as well as the projects as mentioned above that may have led to the reduction of nutrients in the basin.

# Appendix A:


### VLAWMO's 2016 Water Quality Report


(pages 32-34 excerpted from Report regarding Gem Lake)

#### Gem Lake

Gem Lake is within the City of Gem Lake and has no public access. It is 25 acres in size and is 17 feet deep. There has been development along portions of the lake in recent years. In 2000, volunteers noticed a distinct algae bloom and noted that water clarity was getting poorer. Over the 16 years of monitoring data there is a slight up trend in TP levels with a slight down trend in ChIA levels.

Gem Lake has also been included on the Lambert Creek TMDL study for nutrient impairment. Recent years of monitoring data are suggesting that the trend may be heading down for nutrient levels in Gem Lake and the MN Pollution Control Agency will be assessing the data winter of 2017 for removal from the state impaired waters list. The City of Gem Lake, VLAWMO and stakeholders will be working together to implement the TMDL strategies from the approved 2014 report. MNDOT's Hwy 61 ditch work in 2011 has seemed to improve the water quality in Gem Lake.





Gem Lake Data


Gem Lake Historical Avg TP/Chl A/SDT			Date	Reading Depth (Bottom/Middle /Top)	Temp °C	Conductivity (mS/cm)	DO (mg/L)	рН	
		Chl A	Secchi		_				
Year	TP (ug/L)	(mg/m3)	(m)	5/16/2016	b	13.3	0.185	6.83	8.07
1997	54	23	1.2	5/16/2016	m	14.08	0.185	7.11	8.06
1998	33	24		5/16/2016	t	14.31	0.185	7.3	8.15
1999	26	16	1.2	6/10/2016	b	16.16	0.192	1	7.81
2000	36	17	1.1	6/10/2016	m	21.09	0.191	6.93	8.07
2001	56	12	1.8	6/10/2016	t	23.22	0.19	6.79	8.74
2002	39	25	1.3	7/20/2016	b	24.72	0.185	4.66	7.61
2003	52	20	1.4	7/20/2016	t	26.35	0.185	5.92	8.23
2004	49	0	1.5	9/20/2016	b	20.29	0.176	3.28	8.19
2005	43	26	0	9/20/2016	m	20.49	0.176	5.69	8.19
2006	63	25	0	9/20/2016	t	20.58	0.176	5.78	8.15
2007	48	33	1.1						
2008	64	17	1.5						
2009	89	28	1.3						
2010	53	24	1.4						
2011	32	6.4	2.1						
2012	41	11	2						
2013	35	17	2	1					
2014	31	8	2.9	1					
2015	38	23	2.2	1					
2016	30	18	1.6						

Gem Lake YSI data is similar to that of other metro lakes. Conductivity is pretty low which is good
and usually Gem Lake shows signs of stratification. At 17ft, Gem is the deepest lake VLAWMO
monitors. Gem usually has a late season algae bloom and that was the case in 2015. TP and ChlA
levels are well below state standards for the 5<sup>th</sup> year in a row. Hwy 61 was redone in 2011 and
MNDOT did work on the ditches along the Hwy. That work seems to have benefited the water
quality in Gem

SITE	DATE	Secchi (ft)	TP (ug/L)	ChIA (mg/m3)	TKN (mg/L)	NH3 (mg/L)	Cl (mg/L)
Gem	3/28/2016						38
Gem	5/3/2016	8	26	5.1	0.71		
Gem	5/17/2016	9	14	5.3			
Gem	6/7/2016	5	20	9.9	1.1	ND	
Gem	6/21/2016	5.5	16	15.6			
Gem	7/12/2016	3	29	31.1	1.5	ND	
Gem	7/26/2016	4	13	14.4			
Gem	8/2/2016	5.5	25	15.6	0.88	ND	
Gem	8/23/2016	4	38	23.2			
Gem	9/13/2016	3	55	34.2	1	ND	
Gem	9/27/2016	4	59	25.8			

#### Gem Lake 2016 Raw Data


• Nitrogen and ammonia levels are below state standards for Gem Lake.



# Appendix B:


## Highway 61 Reconstruction Plans





PLOTTED/REVISED. 16-MAR-2010


161\_sht\_topol7 d6222161\_sht\_ DISTRICT \*: METRO IPLOT NAME: d6222161\_5 PATH & FILENAME: d62




PLOTTED/REVISED: 16-MAR-2010 10

DISTRICT \*: METRO IPLOT NAME: d622216L\_sht\_topo18 PATH & FILENAME: d622216L\_sht\_topo18dgn

• •




METRO d6222H



15-MAR-2010 PLOTTED/REVISED:

61\_sht\_dr18 d6222161\_sht\_c **METRO** ENAME: DISTRICT \*: IPLOT NAME: PATH & FIL



METRO

. . .